OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 05/15/06

CORNER DESIGNATION: 2N31, L-17, The East One-Quarter Corner of Section 15.

PREVIOUS RENEWALS/SURVEYS ETC.: Corner established by Josiah A. Burnett, under Contract No. 92, dated September 12, 1860. Record states: Set a post for 1/4 Sec. corner, drove charred stake and raised mound with trench, as per instructions.

John Kimbrell reestablished this corner in Survey recorded at Book 1, Page 348. Record states: "Set Stone marked 1/4 in md of earth and stone Pits N & E.

MONUMENT AND ACCESSORIES FOUND: None, falls in farmed ground, corner has been farmed out.

MONUMENT MARKING DETAIL:

T2N R31E

1 4

S15 | S14

2006

PLS 1106

MONUMENT SET:

Re-established corner by single proportionate measure between the recovered or reestablished Northeast and Southeast corners of Section 15. A reestablished corner position, set a 2 3/8" brass cap on 1 1/4" x 30" galvanized iron pipe with cap 15" below ground level. Monument marked as shown in Monument Marking Detail.

From which:

A silver Deep-1 magnet buried 22" below ground level bears North 54° East, 25.5 feet A blue Deep-1 magnet buried 22" below ground level bears South 29 1/2° East, 27.9 feet. A purple Deep-1 magnet buried 22" below ground level bears South 67° West, 36.0 feet. A orange Deep-1 magnet buried 22" below ground level bears North 33° West, 35.8 feet. Buried bearing object signs with all magnets.

LOCATION AND COMMENTS: Corner is located in a farmed field with no other nearby features.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 728246.67E = 8608079.15

FIRM: William R. Wells, PLS

P.O. Box 1696

Pendleton, OR 97801

COMPASS DECLINATION: 18° East

Witnesses: Jason Wells, LSIT

/2N31L17

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

renews 6-30-08