

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 01/23/02

CORNER DESIGNATION: 2N33L25, The East Quarter Corner of Section 13.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Most recent Umatilla County Surveyors recorded survey record: 89-74-C.

MONUMENT AND ACCESSORIES FOUND:

Found 5/8" iron rebar with top 2" above gravel road and bent over. Set a nail at straight location of rebar for the corner tie point.

MONUMENT MARKING DETAIL:

LOCATION & COMMENTS:

Corner located in gravel road.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 729738.72

E = 8682361.66

FIRM/AGENCY: William R. Wells
P.O. Box 1696
Pendleton, Oregon 97801

2N33L25

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

Renews 6-30-02

RECEIVED BY

Umatilla County Surveyor

Date 2-02

By KK

No. 02-43-9