

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

R - 7  
DIAGRAM

**History of original corner establishment:**

The original corner was established by George S. Pershin on September 10, 1878, under GLO contract No. 293, as follows:

Set a stone, 14" x 12" x 7", for the 1/4 section corner.

T2S R30E  
1/4 S20  
S29  
PLS 1636  
2002

**Original corner evidence recovered:**

Found the original corner stone firmly set but tipped to the east. The corner stone is 15" x 12" x 8" and although the stone is coarse, is plainly marked "1/4" on the north face.

**Monument and accessories established to perpetuate the original position of this corner:**

In place of the original corner stone, I set a 1" x 18" flared, galvanized iron pipe 14" into the ground to bedrock. A 2 1/2" brass cap attached to the top of the iron pipe is marked as shown in the diagram above. I bury the corner stone along the east side of the pipe and build a mound of stones around the pipe, from which:

A 5/8" x 24" iron rod, set 23" into the ground with a 3/4" brass washer, marked "PLS 1636 NE", attached at ground level, bears N43° E, 101.1 feet.

A 5/8" x 24" iron rod, set 23" into the ground with a 3/4" brass washer, marked "PLS 1636 SE", attached at ground level, bears S36° E, 133.4 feet,

A 5/8" x 24" iron rod, set 22" into the ground with a 3/4" brass washer, marked "PLS 1636 SW", attached at ground level, bears S21° W, 85.4 feet.

A 5/8" x 24" iron rod, set 21" into the ground with a 3/4" brass washer, marked "PLS 1636 NW", attached at ground level, bears N34° W, 44.5 feet.

I hereby certify the above corner point was perpetuated as hereon described on February 13, 2002. Magnetic declination set in compass: 16°E.

  
*Dennis L. Gaylord*

Renews June 30, 2003

Recorded at the office of County surveyor, County of Umatilla, State of Oregon, on:

RECEIVED BY  
Umatilla County Surveyor  
Date 6-02  
Rec'd By KK  
No. 02-156-R-