


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHMENT:**

Corner not previously established.

T4N R37E Y-09



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

None.

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED**

**TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At position determined by survey, I set a 5/8" x 30" iron pin with a 2 1/2" aluminum cap marked as shown below, 30 inches in the ground, from which:

A 10 inch White Fir bears North 7° East, a distance of 2.55 feet, marked S1/16 S33 BT.

An 9 inch White Fir bears South 24° West, a distance of 8.40 feet, marked S1/16 S32 BT.

I set a fencepost 1 foot South of the monument.

The monument is situate 4.5 feet East of a North/South running fence and 28.9 feet South of the fence intersection running West/South.


I hereby certify that the corner was monumented on July 11<sup>th</sup>, 2013.

Witness: Daniel Inloes

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Jeffrey S. Hsu*  
OREGON  
June 2, 2010  
JEFFREY S. HSU  
83571

Renewal Date: June 30, 2015



I used a steel tape and magnetic compass in the establishment of the new accessories. I use 16° East declination. The distance to the new bearing trees are to a 60d spike driven into the right side of the root crown of the bearing trees. Attached brass washer marked OPLS 83571 to BT Blaze.

**RECEIVED BY**  
Umatilla County Surveyor  
Date: 8/9/2013  
Rec'd By: J. Tolbert  
No.: 13-213-C